## WNP7 Workshop campaign - Clean windshield in front camera area and replace rain sensor

## WNP7 Workshop campaign - Clean windshield in front camera area and replace rain sensor

ID Number	WNP7
Models	Macan (95B)
Model Years	2020
VIN List	Attached
Number of Affected VINs	189
Issue Description	It is possible that dirt has accumulated in the area of the front camera on the affected vehicles due to im- proper cleaning of the windscreen during installation. If this is the case, the function of the camera and rain sensor may be restricted.
	For this reason, the relevant area of the windscreen must be cleaned and the rain sensor must be replaced on the affected vehicles.
What Dealers Should do	Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available. Parts can be ordered via PPL as needed.
TI Number	No. 201-22