

TECHNICAL SERVICE BULLETIN

Classification:	Reference:	Date:
BT22-026	ITB22-044	December 16, 2022

LICENSE PLATE BRACKET INSTALLATION ON FRONT FASCIA

APPLIED VEHICLES: 2022 QX55 (J55)

SERVICE INFORMATION

When performing step 6 of the license plate bracket installation instructions in the owner's manual, it is critical to maintain a 0.79 in. (20 mm) hole when drilling locations © (Figure 1). If a 0.79 in. (20 mm) hole is not maintained, the license plate bracket will not sit flush on the front fascia.




Figure 1

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 16, 2022	ITB22-044	Original bulletin published

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.