

# TECHNICAL SERVICE BULLETIN

Classification: Reference: Date:

AN21-008B NTB21-037B December 19, 2022

## DTCS B2E4B-06, B2E60-06, B2E61-06 STORED IN THE TCU

This bulletin has been amended. See AMENDMENT HISTORY on the last page.

Please discard previous versions of this bulletin.

**APPLIED VEHICLES:** 2021-2023 Rogue (T33)

2021-2022 Sentra (B18) 2022-2023 Pathfinder (R53)

2023 ARIYA (FE0)

#### IF YOU CONFIRM

The customer experiences an issue with the NissanConnect® Service remote commands,

#### **AND**

Any of the following DTCs are present in the Telematics Control Unit (TCU):

- B2E4B-06
- B2E60-06
- B2E61-06

**NOTE:** These DTCs are caused by an issue with a cloud-server that is related to the TCU. The DTC diagnosis was mistakenly added to some ESMs and should be ignored.

#### **ACTION**

- 1. Do NOT replace the TCU. Replacing the TCU will not resolve the concern.
- 2. Send an email to NTB21-037@Nissan-Usa.com.

**IMPORTANT:** The purpose of **ACTION** (above) is to give you a quick idea of the work you will be performing. You MUST closely follow the entire **SERVICE PROCEDURE** as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

### **SERVICE PROCEDURE**

**IMPORTANT:** Do NOT replace the TCU. Replacing the TCU will not resolve the concern.

- 1. Send an email to <a href="https://NTB21-037@Nissan-Usa.com">NTB21-037@Nissan-Usa.com</a>. In the email, please provide the following:
  - Name
  - Phone Number
  - Dealer Name
  - Dealer Code
  - VIN
  - DTC(s) present
  - Photo of the **Unit ID Information** screen (Figure 1).
    - The Unit ID Information screen can be found at: Settings > NissanConnect®
       Services > Unit ID Information.




Figure 1

**NOTE:** Please allow up to 48 business hours (M-F) for an email response with next steps. Do NOT replace any parts.

#### **AMENDMENT HISTORY**

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 6, 2021	NTB21-037	Original bulletin published
August 5, 2021	NTB21-037A	APPLIED VEHICLES revised
December 19, 2022	NTB21-037B	APPLIED VEHICLES revised

2/2 NTB21-037B