

REFERENCE:	TSB: 09-014-22 GROUP 09 - Engine	Date:	December 14, 2022	REVISION:	-
VEHICLES AFFECTED:	<p>2021 - 2022 (DD) RAM 3500 Cab Chassis 2021 - 2022 (DP) RAM 4500/5500 Cab Chassis This bulletin applies to vehicles built on or after June 26, 2021 (MDH 0626XX) and on or before April 11, 2022 (MDH 0411XX) equipped with a 6.7L I6 Cummins Turbo Diesel Engine (Sales Code ETN).</p>	MARKET APPLICABILITY:			
CUSTOMER SYMPTOM:	Installation of particulate matter sensor.				
CAUSE:	Vehicles were built without particulate matter sensors.				

DISCUSSION:

This bulletin involves extending the warranty on the DPF.

NOTE: This is an “Information Only” Technical Service Bulletin to inform the dealer of this warranty extension.

POLICY:

This warranty extension coverage period is 1 Year / Unlimited miles from the date of installation of the Particulate Matter Sensor, under the Y43 Emissions Recall. See Warranty Bulletins: U.S. D-22-16, Canada SAB 2022-29, and International ID-22-22, for details associated with the warranty extension.

NOTE: For vehicles covered under this warranty extension, use the standard warranty LOPs.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.