

Technical Journal

TITLE:

Call button in the OHC might not be lit

REF NO: TJ 36447.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2022-12-06	STATUS DATE: 2022-12-19
FUNC GROUP: 3900	FUNC DESC: Media, navigation and communication	Page 1 of 2	

“Right first time in Time”

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If the On Call / “Connect” / “Talk Bubble” button on the Overhead Console is not lighting up, please see the information listed in the Service section.

OHC = Over Head Console

CSC Customer Symptom Codes

Code	Description
JG	Volvo On Call/Other Volvo On Call problems

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2023-9999		-	202222-999952
225							2023-9999		-	202222-999952
227							2023-9999		-	202222-999952
235							2022-9999		-	202122-999952
236							2022-9999		-	202122-999952
238							2022-9999		-	202122-999952
246							2022-9999		-	202122-999952

Technical Journal 36447.1.0

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536							2021-9999		-	202037-999952
539							2022-9999		-	202139-999952

SERVICE:

The described symptom does not affect the performance of the vehicle's connectivity functions. The symptom appears intermittently.

A solution for this issue will be available in 2023 Q1.

Please do not exchange any parts due to this issue. This is a software related issue and will not be solved by a parts exchange.

VEHICLE REPORT:

N/A