



Bulletin No.: PIP5892

Published date: N/A

Preliminary Information

PIP5892 Malfunction Indicator Lamp Illuminated with DTC P0234 post Turbocharger Replacement

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
BUICK	Encore GX	2020 - 2022	All	All	1.2L (LIH)	All
CHEVROLET	Trailblazer	2021 - 2022	All	All	1.2L (LIH)	All

Involved Region or Country	North America
Condition	MIL illuminated with DTC P0234 post Turbocharger Installation.
Cause	GM is aware of this concern and working to root cause.

Correction:

Some customers may comment that the Malfunction Indicator Lamp (MIL) is illuminated with DTC P0234 (Engine Overboost) set current or in history.

Reduced Power may also occur.

First, clear the DTC.

Use GDS2 to perform the Intake System Learned Values Reset.

If the code is not current, or does not reset during a road test, advise the customer that GM is aware of this concern and working to root cause.

Release the vehicle to the customer.

This Preliminary Bulletin will be updated with further information as it becomes available.

Version History

Version	1
	12/01/2022 - Created on.



GENERAL MOTORS