

# SERVICE BULLETIN 598 - TIGER 1200 BEVEL BOX BREATHER



## Notice Information

Ref	21724
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

**TOL NOTICE (USCA) – June 17, 2022**

**TOL Ref. #21724 - SVC**

## SERVICE BULLETIN 598 – TIGER 1200 BEVEL BOX BREATHER

Dealers are requested to remove the rear bevel box breather and refit with sealant as described in the procedure attached.

Subject: Rear Bevel Box Breather				
Bulletin Number	Models Affected	VIN Range		Markets Affected
598	Tiger 1200 GT	From AV5527	To BD8324	All Markets
	Tiger 1200 GT Pro			
	Tiger 1200 Rally Pro			
	Tiger 1200 GT Explorer			
	Tiger 1200 Rally Explorer			

The complete Service Bulletin 598 and instructions can be found attached and at the TriumphOnline.net (TOL) [Service Bulletin Page](#). Please print and ensure that all relevant staff in your dealership/market are familiar with the action.

Warranty Claim Instructions				
Bulletin Number	Fault Code	Repair Code	Description	Repair Allowance Time
598	20580998	99598	Refit bevel box breather	0.08 Hrs

**Reminder:** use the "[VIN Enquiry](#)" function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

**Customer Contact Instructions**

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

-

**Notes:**

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on [www.triumphonline.net](http://www.triumphonline.net).

-

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.