

Service and Parts Business

Technical Journal

TITLE:					
Charge lid difficult to open/close					
REF NO:	ISSUING DEPARTMENT:	CAR M	ARKET:		
TJ 36439.1.0	Technical Service	United States and Canada			
	PARTNER:	ISSUE DATE:	STATUS DATE:		
3 US 7	7510 Volvo Car USA	2022-12-21	2023-01-03		
FUNC GROUP:	FUNC DESC:				
8331	Tank hatch with hinge	Page 1 of 5			

"Right first time in Time"

Attachment

File Name	File Size		
TJI-525490-1_1_0_en-US.pdf	0.4479 MB		

DESCRIPTION:

If the customer experiences that the charge lid is difficult to open/close, follow advice under service.

CSC Customer Symptom Codes

Code	Description
YX	Charging socket/Lock does not lock/unlock/Unsure when/at all times
8H	Fuel-filler door/Hard/impossible to open
8I	Fuel-filler door/Hard/impossible to close
UI	Fuel-filler door/Locking does not work

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	ED	E400V6					2021-2023		-	202017-202250
536	EF						2021-2023		-	202017-202250
539							2022-2023		-	202139-202250

Produced and printed in the USA and available as an electronic document. @ 2023 VOLVO CAR USA, LLC

Technical Journal 36439.1.0

SERVICE:

Adjust the charge lid according to attached method.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 99921-2 General reimbursement acc. to TJ/QB

VST Operation Number

VST Operation Number	Description
99921-2	General reimbursement acc. to TJ/QB

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8331.


To view TJ attachment continue to next page. This TJ has one attachment.

vor		/olvo	Car Customer Service	TJ	Instructio	on VCC-525490-1
Title		Charge (Connector Door		Page	1 (3)
Action	l	Adjustme	ent		Operation nu	umber:
Issue	Date		Reason			
1	2022-1	12	First issue			

Affected vehicles

Model year	Model	Engine
2022, 2023	C40	E400V2, V6
2021, 2022,	XC40	E400V2, V6
2023		


Color symbols




Removal

Release the catch. Remove the marked part.







Installation

To install, reverse the removal procedure.