

PD Model 1610 Inverters with Error code E-8, E-9

If you have a Progressive Dynamics model PD1610 Inverter and you are getting either an E-8 or E-9 code, the cause may be a mismatched Remote. The older PD 1610 Inverters used a remote that has a green PC board inside the remote. The newer ones have a blue PC board inside the remote. If you use a green PC board remote, with a newer Inverter you could get the above codes. If you use a blue PC board remote with an older Inverter, you could get the above error codes as well. If you are getting the error codes, please check the PC board color which is visible where the cable connects to the remote. Below are images of the two different PC boards. If swapping the remotes, please note what color PC board you have and have tried, as well as the serial number of the PD Inverter, before you contact Forest River.

Note: The Inverter will still function on all settings, it will keep displaying the error code, telling you the remotes are not properly matched.

