

## **SSM 51299**

### **2022 Maverick - Headlamps Turn On By Themselves When Vehicle Is Off, DTC B1533**

Some 2022 Maverick vehicles may exhibit a condition of intermittent headlamp operation while the vehicle is OFF and have diagnostic trouble code (DTC) B1533 stored in the body control module (BCM). This may be due to the internal logic within the headlamp switch. To correct this condition, replace the headlamp switch (11654). Refer Workshop Manual, Section 417-01. For claiming, use causal part 11654 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.