

RECENTLY UPGRADED CAMPAIGN N733

SERVICE ACTION N733 - ACTIVE ROLL CONTROL MODULE (ARCM) INITIALIZATION FAILURE	
AFFECTED MODELS	22-23MY Range Rover
VOLUME AFFECTED	US 2843 CAN 353
REPAIR	The front and rear ARCMs, in a small percentage of cases, are susceptible to intermittent initialization failure when the vehicle is started, and an amber suspension fault warning lamp may be illuminated of the Instrument Cluster Panel. Retailers are to update to both the front and rear ARCM ECU before vehicle sale.
REPAIR TIME	0.4 hrs + DIDO
CAMPAIGN LAUNCH	ONP Service Action January 12th, 2023
Notes	This was initially launched in September 2022 as an Update Prior to Sale campaign. In December 2022 it was upgraded to a Customer Satisfaction Program with larger affected population. It is now being further upgraded to an owner notified service action. Customers will be notified by mail to make service appointments.