

Reference	SSM75924
Models	New Range Rover Sport / L461
Title	23MY - Rear stop lamp DTC Body Control Module (BCM) flagged with no customer symptom.
Category	Diagnostic Software Hardware
Last modified	30-Jan-2023 00:00:00
Symptom	000101 Diagnostic Concerns

Content

Issue:

JAGUAR LAND ROVER is investigating technician reports of DTC: C111A-23 / C111B-23 within the BCM which maybe found on a DTC read, however no customer symptom / warning message is present.

Cause:

NAS calibration of the Directional indicator (DI) uses the Brake function as part of the DI.

Action:

Please do not replace any parts.

This is a known issue.

Please clear the DTC as per the DTC help text in TOPIx

Thank for your assistance in this matter.

anBhdHRicn7MjAyMy0wMj0wMj0wNDowMDoxM44NTa0zEzNi4yMjYyNzluMTI3Ow==