

# WNL4 Workshop Campaign - Replacing front bumper

---

## Update 2/3/23

Please be advised that an updated TI for WNL4 is available in PCSS and the [AfterSales Document Database](#).

## WNL4 Workshop Campaign - Replacing front bumper

ID Number	WNL4
Models	Taycan 4S (Y1A) / Taycan Turbo (Y1A) / Taycan Turbo S (Y1A) Taycan Turbo Cross Turismo (Y1B)
Models Years	2020 - 2021
VIN List	Attached
Number of Affected VINs	269
Issue Description	<p>It is possible that a welded joint on the bumper does not meet the required specifications on the affected vehicles.</p> <p>For this reason, the front bumper on the affected vehicles must be replaced with one that meets the required welding specifications.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. <b>As of the time of this posting, the repair is immediately available. Parts can be ordered as normal via PPL.</b></p>
TI Number	<a href="#">No. 154-22</a>
Customer Notification	To be added at a later date.

## Required parts

Vehicles with campaign scope 1 and 2:

Part number	Designation	Quantity/vehicle	Parts return*
V04015805	Cross member	1 pc(s)	No
9J1805230	Seal	2 pc(s)	No

## WNL4 Workshop Campaign - Replacing front bumper

9A700744300	Screw M10 x 40	8 pc(s)	No
N 91033501	Screw M6 x 22	2 pc(s)	No

Vehicles with campaign scope 3:

Part number	Designation	Quantity/vehicle	Parts return*
9J0805241A	Cross member	1 pc(s)	No
9J1805230	Seal	2 pc(s)	No
9A700744300	Screw M10 x 40	8 pc(s)	No
N 91033501	Screw M6 x 22	2 pc(s)	No

Vehicles with campaign scopes 4 to 12:

Part number	Designation	Quantity/vehicle	Parts return*
V04015805	Cross member	1 pc(s)	No
9J1805230	Seal	2 pc(s)	No
9A700744300	Screw M10 x 40	8 pc(s)	No
N 91033501	Screw M6 x 22	2 pc(s)	No

\*The parts must be stored until the related warranty or campaign claim has been credited . If, with the credit note, a barcode is generated , the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the replacement parts process or be scrapped.

## Warranty processing

Validity:

This workshop campaign will be carried out through to December 1st, 2027 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

Scope 1: Replacing front bumper

- Taycan (Y1A) with LED headlights (PDLS Plus) (M no. 8IS)

Damage Code	WNL4 66 000
Repair Code	2
Labor time	441 TU

Scope 2: Replacing front bumper

- Taycan (Y1A) with LED matrix headlights (PDLS Plus) (M no. 8IU and 8JU)

Damage code:	WNL4 66 000
Repair code:	2
Labor time:	456 TU

### Scope 3: Replacing front bumper

- Taycan (Y1B) with LED matrix headlights (PDLS Plus) (M no. 8IU and 8JU)

Damage code:	WNL4 66 000
Repair code:	2
Labor time:	456 TU

### Scope 4 to 7: Replacing front bumper

- Taycan (Y1A) with LED headlights (PDLS Plus) (M no. 8IS)

Damage Code	WNL4 66 000
Repair Code	2
Labor time	551 - 629 time units

### Scope 8 to 12: Replacing front bumper

- Taycan (Y1A) with LED matrix headlights (PDLS Plus) (M no. 8IU and 8JU)

Damage code:	WNL4 66 000
Repair code:	2
Labor time:	550 - 628 time units

## Customer mobility

If requested, mobility for the affected customer is to be ensured with a suitable replacement vehicle. Please invoice this additional service again via WWS with the campaign scope.

---

### Attachments

1. [VIN\\_List\\_Report\\_WNL4\\_2023-01-13 WITH SCOPES.xlsx](#)
2. [VIN\\_List\\_Report\\_WNL4\\_2023-01-13\\_V2.xlsx](#)