

Published date: 01/30/2023

Preliminary Information

PIT5974 Outside Mirror Puddle Lights Only Remain On For A Few Seconds

<u>Proactive</u>

<u>Models</u>

Model:	Model Years:	VIN:		Engine	Transmissions
		from	to	Engine.	Transmissions:
Silverado 1500 New (RPO J22, VIN Digit 5 = A or D)	2022	All	All	All	All
Silverado 1500	2023	All	All	All	All
Sierra 1500 New (RPO J22, VIN Digit 5 = H or U)	2022	All	All	All	All
Sierra 1500	2023	All	All	All	All
	Silverado 1500 New (RPO J22, VIN Digit 5 = A or D) Silverado 1500 Sierra 1500 New (RPO J22, VIN Digit 5 = H or U)	Silverado 1500 New (RPO J22, VIN Digit 5 = A or D) 2022 Silverado 1500 2023 Sierra 1500 New (RPO J22, VIN Digit 5 = H or U) 2022	Model: Model Years: from Silverado 1500 New (RPO J22, VIN Digit 5 = A or D) 2022 All Silverado 1500 New (RPO J22, VIN Digit 5 = H or U) 2023 All Sierra 1500 New (RPO J22, VIN Digit 5 = H or U) 2022 All	Model: Model Years: inform to Silverado 1500 New (RPO J22, VIN Digit 5 = A or D) 2022 All All All Silverado 1500 New (RPO J22, VIN Digit 5 = H or U) 2023 All All All Silverado 1500 New (RPO J22, VIN Digit 5 = H or U) 2022 All All All	Model:Model Years: $inormalEngine:fromtofromtoSilverado 1500 New (RPO J22, VIN Digit 5 = A or D)2022AllAllAllSilverado 1500 New (RPO J22, VIN Digit 5 = H or U)2022AllAllAllSierra 1500 New (RPO J22, VIN Digit 5 = H or U)2022AllAllAll$

Involved Region or Country	North America
Condition	Some customers may comment when the puddle lights, located on the bottom of the outside mirrors, turn on that they only stay on for a few seconds and then turn off.
Cause	The cause of this condition could be an issue with the Lighting Control Module calibrations.

Correction:

GM engineering is aware of this issue and working on a fix. In the meantime, do not replace any parts or perform any programming events.

Version History

Version	1
Modified	01/30/2023 - Created on.



© 2023 General Motors. All Rights Reserved.