

## GPOP - Issue Review System

**Part Number:** 68402778A\$, 68403802A\$, 05064358A\$, 52851560A\$, 68043032A\$,  
68409853A\$, 05091019A\$, 04749193A\$, 68347026A\$,

**Part Description:** SPEAKER, 6"x9" Right or Left

**Issue Description:** For a buzz, squeak or rattle (BSR) concern coming from the door speaker area please check that when removing the door trim panel, it doesn't come off with the two-stage push-pin clips (in vehicles that have this type of clip, not the ones with a screw) ONLY with its outer clip. If found to have any clip coming with both inner and outer part, please replace the clips with new ones (as old ones might have already been deformed) and reinstall the door trim. Follow Service Library procedure to properly remove/install the door trim. For this issue send feedback via email to FCA Redacted Content. If no response in 15 minutes, proceed with repair. Contact Us for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking systems.