

REFERENCE:	TSB: 08-001-23 GROUP 08 - Electrical	Date:	January 4, 2023	REVISION:	-
VEHICLES AFFECTED:	2023 (WS) Grand Wagoneer/Wagoneer This bulletin applies to vehicles equipped with Quadra-Lift™ Air Suspension (Sales Code SER)	MARKET APPLICABILITY:			
		<input checked="" type="checkbox"/> NA <input type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input checked="" type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> CH			
CUSTOMER SYMPTOM:	There are no fixes for customers facing symptoms contained in this software. The ASCM software update is being released as a generic release to support ASCM replacement only in service.				
CAUSE:	ASCM software				

REPAIR SUMMARY:

This bulletin involves reprogramming the ASCM with the latest available software.

CAUTION! Only if ASCM replacement is necessary should the module need updated with this software. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 08 - Electrical / 8E - Electronic Control Modules / Module, Air Suspension Control (ASCM) / Removal and Installation.

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.