



GROUP	MODEL
ENG	2023MY Seltos (SP2)
NUMBER	DATE
242	February 2023

TECHNICAL SERVICE BULLETIN

SERVICE ACTION: COOLANT RESERVOIR CAP INSPECTION & REPLACEMENT (SA527)

SUBJECT:

This bulletin provides information to inspect and if necessary, replace the coolant reservoir cap on some 2023MY Seltos (SP2) vehicles produced from October 26, 2022 through November 11, 2022 which may have the incorrect coolant reservoir cap installed. Some vehicles may have had a metal cap installed during assembly. Follow the procedure outlined in this bulletin to confirm the vehicle is equipped with the correct coolant reservoir cap and if needed, install the correct plastic coolant reservoir cap. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs below.

Affected VIN List

KNDETCA22P7421234	KNDETCA26P7421785
KNDETCA23P7421341	KNDETCA27P7421276
KNDETCA27P7421245	KNDETCA27P7421438
KNDETCA20P7421233	KNDETCA28P7421044
KNDETCA21P7421063	KNDETCA28P7421075
KNDETCA22P7421704	KNDETCA29P7421215
KNDETCA22P7421850	KNDETCA29P7421330
KNDETCA24P7421896	KNDETCA27P7421858
KNDETCA25P7421101	KNDETCA20P7421846

NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA527.

Inspection & Repair Procedure:

1. Inspect the coolant reservoir cap and confirm it is equipped with the correct plastic cap:
 - If the reservoir cap is the plastic type shown on the right (OK), then no further action required. This action is complete.



- If the reservoir cap is the metal type shown on the right (NG), then replace the coolant reservoir cap with the plastic type shown below.




SUBJECT:

COOLANT RESERVOIR CAP INSPECTION & REPLACEMENT (SA527)**AFFECTED VEHICLE RANGE:**

Model	Production Date Range
Seltos (SP2)	October 26, 2022 to November 11, 2022

REQUIRED PART:

Part Name	Part Number	Figure	Qty.
Coolant Reservoir Cap	25330 D9000		1

WARRANTY INFORMATION:**N Code: N99 C Code: C99**

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	25330 D9000	0	(SA527) Coolant Reservoir Cap Inspection	220162R0	0.1 M/H	N/A	0
			(SA527) Coolant Reservoir Cap Inspection & Replacement	220162R1	0.2 M.H	25330 D9000	1

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA527 when accessing the WebDCS system.