

# WNK6 Workshop campaign - Exchanging spreader device (actuator)

---

## WNK6 Workshop campaign - Exchanging spreader device (actuator)

ID Number	WNK6
Models	718 (982) 911 (992) Panamera (971) Cayenne (9YA / 9YB) Taycan (Y1A / Y1B / Y1C)
Model Years	2021-2022
VIN List	Attached
Number of Affected VINs	3,187
Issue Description	<p>There is a possibility that the spreader device (actuator) for the electric parking brake does not meet the required specifications on the affected vehicles.</p> <p>If this is the case, cup springs can potentially break in the spreader device over a longer service life, and this can result in function restrictions when the electric parking brake is actuated.</p> <p>To prevent this from happening, the spreader device (actuator) on the affected vehicles must be replaced with a spreader device that meets the required specifications.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. <b>As of the time of this posting (2/14/23), the repair is immediately available.</b></p> <p><b>Parts can be ordered via PPL as needed.</b></p>
TI Number	<a href="#">No. 166-22</a>

## Required parts

For details of the required part numbers, see Technical Information.

### Parts return request

The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the replacement parts process or be scrapped.

## Warranty processing

### Validity:

This workshop campaign will be carried out up to February 2nd, 2028 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

### Scope 1 - 36:

Damage Code	WNK6 66 000
Repair Code	2
Labor time	113 - 259 TU

Please enter the campaign carried out in the warranty and maintenance booklet for the vehicle.

## Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service via WWS with the campaign scope.

---

## Attachments

- [1. VIN\\_List\\_Report\\_WNK6\\_2023-02-14 With Scopes.xlsx](#)
- [2. VIN\\_List\\_Report\\_WNK6\\_2023-02-14\\_V2.xlsx](#)