

WNT0 Workshop campaign - Re-programming air-conditioning system control unit

WNT0 Workshop campaign - Re-programming air-conditioning system control unit

ID Number	WNT0
Models	Taycan (Y1A/Y1B/Y1C)
Model Years	2023
VIN List	Attached
Number of Affected VINs	103
Issue Description	<p>It is possible that the base software programmed on the air-conditioning system control unit does not meet the required programming data security specifications on the affected vehicles.</p> <p>This has no functional effects for the customer.</p> <p>To ensure that the base software programmed on the air-conditioning system control unit meets the required specifications, the control unit must be re-programmed with an updated data record.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting (2/15/23), the repair is immediately available.</p>
TI Number	No. 235-22

Required software

PIWIS Tester 3 test software version	41.700.020 (or higher)
--------------------------------------	------------------------

Warranty processing

Validity:

This workshop campaign will be carried out up to December 29, 2027 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WNT0 66 000
Repair Code	1
Labor time	39 TU

Please enter the performed campaign in the Warranty and Maintenance booklet for the vehicle.

Attachments

- [1. VIN_List_Report_WNT0_2023-02-15_V2.xlsx](#)