

UPDATE PRIOR TO SALE CAMPAIGN N750 FRONT SHOCK ABSORBER INSTALLATION

UPS CAMPAIGN N750 – FRONT SHOCK ABSORBER INCORRECT INSTALLATION	
AFFECTED MODELS	23MY Range Rover, Range Rover Sport
VOLUME AFFECTED	US 88 CAN 10
REPAIR	On certain 23MY Range Rover and Range Rover Sport models, the left-hand front shock absorber may not be fully installed into the suspension yoke casting. Approx. 15% of vehicles are expected to fail an inspection procedure. These vehicles will require a reset of the shock absorber into the yoke to the correct depth using special tools from the required tools list, together with replacement nut and bolt hardware.
REPAIR TIME	Inspection only 0.2 hrs. Inspection and repair 0.5hrs + DIDO
CAMPAIGN LAUNCH	February 7 <sup>th</sup> , 2023
Notes	Retailers should check the warranty portal to confirm affected VIN and following the bulletin service procedure, inspect/repair all affected vehicles before sale and delivery.