

POWERTRAIN – MIL P0128-00 AND POOR CABIN HEATING - P4

Customer Voice:

- Customer reports, Engine Light is on and poor cabin heating.

Technical Description:

- Diagnostic Trouble Code (DTC) P0128-00 Coolant Thermostat (Coolant Temperature Below Thermostat Regulating Temperature) is also present in the Powertrain Control Module (PCM).

Status:

- Confirm the vehicle symptoms as reported.
 - Replace the Thermostat Housing as per TOPIx WSM section: 303-03 ENGINE COOLING - INGENIUM I4 2.0L PETROL.
 - Take a sample of coolant in a (150 ml) sample bottle.
 - Raise an ePQR, quoting this SSM, along with the repair.

Refer to SSM 75918 / SSM 75919

18-23MY Range Rover, Range Rover Sport, RR Velar, RR Evoque, Land Rover Defender, Discovery, Discovery Sport
18-23MY E-PACE, F-PACE, XE, XF

