

Accessory Integrated Air Compressor Operational Issues

Customer Voice:

- A customer may complain that the accessory fitted air compressor is inoperative and or displays an error code.

Technical Description:

- For the accessory integrated air compressors (VPLES0574 or VPLES0617) this may be caused by the compressor software.

Status:

- Revised Integrated Air Compressor (IAC) software has been developed to address this concern.
- SSM 75556 has been published to provide address this concern and has recently been updated.
- Should a customer express a concern, please refer to this SSM.
- IACs that were replaced under warranty and returned for analysis have been found not to have had the software updated.
- Please ensure the IAC software has been updated and that an operational issue still exists before replacing the compressor.

20-23MY Defender

