Reference	SSM75949
Models	Range Rover / L405
Title	L405 Tailgate will not close due to anti-trap false signal
Category	Body
Last modified	24-Feb-2023 00:00:00
Symptom	112000 Latches/Locks & Security
01	In a constant of the constant

Content <u>Issue</u>:

JAGUAR LAND ROVER is investigating customer / technician reports of the tailgate not closing due to anti-trap sensor false signal. All sensors sent back to JLR were No Fault Found (NFF). The connection of the anti-trap sensor to the harness is suspected to be the main cause of the issue and has been noticed before on multiple vehicles.

Cause:

Suspected poor connection between anti-trap sensor and harness

Action:

Please carry out the following:

- · Confirm vehicle symptoms as reported
- Take photographs of the connection between anti-trap sensor and harness
- Disconnect and reconnect the anti-trap sensor to the harness

Attach all photographs to an ePQR if the customer symptom(s) have been resolved, quoting this SSM, along with the repair.

Thank you in advance for your assistance with this matter.

anBhdHRlcnM7MjAyMy0wMy0wM1QxODoyODozNi45NzlaOzEzNi4yMjYuNzluMTl3Ow=