



Preliminary Information

PIT5980 Service Instrument Cluster Message After 30 minutes of Ignition On with DTC U3000 SYM06

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2023	All	All	All	All
GMC	Sierra 1500	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	RPO UDV
Condition	Some customers may comment on a Service Instrument Cluster Message displayed in the DIC after the ignition has been on for approximately 30 minutes. All Instrument Cluster functions will operate normally, except for the Service Instrument Cluster Message being displayed. When checking for DTC's a U3000 06 will be found in the IPC.
Cause	The cause of this concern could be an issue with the IPC software.

Correction:

To correct this concern, reprogram the Instrument Panel Cluster with the latest software available in SPS following SI procedure: P16 Instrument Panel Cluster Control Module: Programming and Setup.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Time

Version History

Version	1
Modified	02/07/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.