

Published date: 02/7/2023

Preliminary Information

PIT5927B Unable to dismiss Turn By Turn Directions From The DIC

<u>Proactive</u>

<u>Models</u>

Brand:	Model:		Model Years:	VIN:		Enginet	Transmissions:	
Di dilu.				from	to	Engine:	Transmissions.	
Chevrolet	Silverado		2021 - 2023	All	All	All	All	
GMC	Sierra		2021 - 2023	All	All	All	All	
Involved Region o	or Country	North America						
Additional Options (RPO) IOS		IOS, L	OS, UE1, and UDD					
		1	Customers may comment that they are unable to cancel or dismiss Turn-By- Furn directions on the DIC.					
Cause Engir		Engin	ngineering has Identified a software concern.					

Correction:

Engineering is aware of the concern and working on the field fix.

This PI will be replaced by a Service Bulletin when a fix is made available.

Until a fix is available, the concern can be corrected by turning off the ignition and opening the door to cancel RAP after reaching the destination or after canceling the TBT directions on the radio.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Op	Description	Time			
3487588*	Turn By Turn does not dismiss on DIC	.2 Hr.			
*This is a unique Labor Operation for Bulletin use only.					

Version History

Version	3
Modified	07/05/2022 - Created on.
	10/28/2022 - Updated to add Labor Operation.
	02/02/2023 - Updated to add 2023 Model Year



© 2023 General Motors. All Rights Reserved.