



Preliminary Information

PIT5744C Disabling Side Blind Zone Alert and/or Park Assist Systems When Removing Pickup Box and/or Bumper

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
Chevrolet	Silverado	2020 - 2023	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All
GMC	Sierra	2020 - 2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UD5, UD7, or UKC
Condition	A customer may request the pickup box and rear bumper be removed to install an aftermarket bed or body. If the vehicle is equipped with Side Blind Zone Alert (UKC) or Park Assist (UD5/UD7) there will be "Service" messages displayed on the DIC due to missing modules and sensors after the box and rear bumper are removed.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 168. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

Version	4
Modified	05/26/2020 - Created per BQM Kevin Minor request. 03/5/2021 - Added 2021 Model Year 01/14/2022 - Added 2022 Model Year 02/27/2023 - Added 2023 Model Year



GENERAL MOTORS