

SERVICE BULLETIN 600 - SPEED TRIPLE 1200 RS & RR DETENT ARM AND SPRING REPLACEMENT



Notice Information

Ref	23398
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – February 2, 2023

TOL Ref. #23398- SVC

SERVICE BULLETIN 600 – SPEED TRIPLE 1200 RS & RR DETENT ARM AND SPRING REPLACEMENT

Dealers are requested to install a replacement detent arm and detent spring as described in the procedure attached for affected models listed below.

Note: Please see page 6 of the attached [Service Bulletin 600](#) regarding replacement fixing (hardware) in the spares kit. The original bolt may be used with replacement kit when following the approved method in the instructions.

Reminder: use the '[VIN Enquiry](#)' function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

Detent Arm and Spring Replacement			
Bulletin Number	Models Affected	VIN Range	Markets Affected
600	Speed Triple 1200 RR Speed Triple 1200 RS	Up to BA0561	All markets except Brazil

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Identification of Affected Motorcycles

Speed Triple 1200 RR and Speed Triple 1200 RS motorcycles in the above VIN range.

Note:

- **Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.**
- **Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.**

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.