



GROUP	MODEL
TRA	2021-2023MY K5 (DL3a) and 2021-2022MY Sorento (MQ4a) w/2.5L T-GDI w/DCT
NUMBER	DATE
101 (Rev 1, 09/02/2022)	August 2022

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: 8-SPEED DUAL CLUTCH TRANSMISSION (DCT) S/W LOGIC IMPROVEMENT (SA502)

NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin.

This bulletin provides information on the software logic of the A/T system in certain 2020-2022 MY K5 (DL3a) and 2021-2022MY Sorento (MQ4a) equipped with Theta 2.5L T-GDI engine w/ 8-Speed DCT. The affected vehicles may experience gear-shifting condition while driving to the point of clutch oil flow consumption immediately after starting. In some cases, the driver may receive a transmission error message and/or MIL ON with P086800 stored. Follow the procedure in this publication to apply the improved logic to the 'A/T' system using the KDS. For more information, see the procedure as described in this bulletin. For confirmation that the latest reflash has been applied to the vehicle, verify the ROM ID using the table on page 3 of this bulletin. Before performing the procedure, verify that the vehicle is included in the list of affected VINs.

DTC Description:

P086800 - Transmission

Country	Model	Production Date Range
(Group 1 VINs)	Sorento (MQ4a)	September 16, 2020 to August 11, 2022
(Group 2 VINs)	K5 (DL3a)	September 16, 2020 to August 4, 2022
SA502B	Sorento (MQ4a)	June 21, 2022 to August 24, 2022
(Group 2 VINs)	K5 (DL3a)	August 5, 2022 to August 24, 2022

NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA502.

SUBJECT:

SERVICE ACTION: 8-SPEED DCT S/W LOGIC IMPROVEMENT (SA502)**AFFECTED VEHICLE RANGE:**

Group	Model	Production Date Range
Group 1	Sorento (MQ4a)	October 26, 2020 to August 11, 2022
	K5 (DL3a)	November 16, 2020 to August 4, 2022
Group 2	Sorento (MQ4a)	June 21, 2022 to August 24, 2022
	K5 (DL3a)	August 5, 2022 to August 24, 2022

REQUIRED TOOL:

Tool Name	Figure	Comments
KDS		Kia Diagnostic System

WARRANTY INFORMATION:**N Code: N99 C Code: C99**

Model	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
MQ4a DL3a	V	954A1 2N180	0	(SA502A) DCT Software Update Group 1 VINs	220A13R1	0.5 M/H	N/A	0
				(SA502B) DCT Software Update Group 2 VINs	220A14R1			

Note: Manually enter sublet code 'X2' for reimbursement of one roundtrip rideshare expense or up to three (3) days of rental expense, with supporting documentation.

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA502 when accessing the WebDCS system.