

105 Second Street NW
Red Bay, Alabama 35582
tiffinmotorhomes.com



Phone: 256-356-8661
Fax: 256-356-8219
info@tiffinmotorhomes.com

VIN:

Ford NHTSA Recall # 22V-731
Ford Safety Recall Notice 22S62

March 15, 2023

Ford F-53 Chassis Rear Stabilizer Bar Attachment

Dear Tiffin Motorhome Customer,

Please see the letter printed on the reverse from Ford Motor Company about a safety recall Ford released that is applicable for the VIN listed above. For any questions regarding this safety recall, please contact Ford Motor Company's Motorhome Customer Assistance Center at 1-866-906-9811. Representatives are available 24 hours a day.

Thank you for your attention to this matter,

Tiffin Motorhomes Recall Department



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121-1904



771794483954

136/00000028/28



TIFFIN MOTORHOMES INC
105 2ND ST NW
RED BAY, AL 35582-3859

March 2023

***** IMPORTANT SAFETY RECALL *****

Safety Recall Notice 22S62 / NHTSA Recall 22V731

Your Vehicle Identification Number (VIN): See Listing

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists with your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue? On your vehicle, the rear stabilizer bar attachment bracket(s) may break and separate from the vehicle during usage.

What is the risk? If the rear stabilizer bar attachment bracket(s) break or separate from the vehicle, the driver will not experience a sudden change in vehicle dynamics and the vehicle will remain stable. However, a separation of the attachment bracket while driving can create a potential road hazard for other road users, increasing the risk of a crash.

What will Ford and your dealer do? Parts are now available to repair your vehicle. Ford Motor Company has authorized your dealer to replace the rear stabilizer bar brackets free of charge (parts and labor).

How long will it take? The time needed for this repair is less than half a day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What should you do? Please call your dealer without delay and request a service date for Recall 22S62. Provide the dealer with your VIN, which is printed near your name at the beginning of this letter.

Ford has not issued instructions to stop driving your vehicle under this safety recall. You should contact your dealer for an appointment to have your vehicle remedied as soon as practicable.

If you do not already have a servicing dealer, you can access ford.com/support for dealer addresses, maps, and driving instructions.

Ford Motor Company wants you to have this safety recall completed on your vehicle. The vehicle owner is responsible for making arrangements to have the work completed. Ford Motor Company can deny coverage for any vehicle damage that may result from the failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.