



Service Bulletin

Bulletin No.: 23-NA-037

Date: March, 2023

INFORMATION

Subject: Information on Light Duty Silverado and Sierra Correct Spare Tire Size For Accessory Wheel Packages

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Silverado 1500 | 2021 | 2023 | | | All | All |
| GMC | Sierra 1500 | | | | | | |

| | |
|----------------------------|--|
| Involved Region or Country | |
|----------------------------|--|

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

This bulletin offers information on Accessory Wheel(s) Spare part numbers for the corresponding RPO's.

The spare tire and wheel will have to be replaced with the production 18" spare to provide the correct circumference tire to work properly with the ABS and stability system.

Important: This is not a warranty concern but an option and any action taken would be a customer pay event.

Parts Information

Important: Purchase of Tire Placard Label Insert P/N 19206430 required to record spare tire size and pressure.

| Size | RPO | Wheel Kit # | Required Spare |
|------|----------|-------------|----------------------------------|
| 18 | SE5 | 84641199 | QAQ — 23376705 |
| | SKY | 84040796 | RHM — 23376688 XCQ — 23376706 |
| 20 | SEH | 84939095 | QAQ — 23376705 |
| | SEM | 84582671 | |
| 22 | SF1 | 84799388 | QAQ — 23376705 |
| | SF0 | 84799392 | |
| | SEZ | 84799387 | |
| | SGM | 84799395 | |
| | SHD | 84799396 | |
| | SEU | 84799389 | |
| | SES | 84799393 | |
| | SEV | 84799390 | |
| | SEW | 84799391 | |
| | SSI | 84802385 | |
| | SSW | 84802384 | |
| SRL | 84582669 | | |
| SRV | 84802386 | | |

| | |
|----------|-------------------------|
| Version | 1 |
| Modified | Released March 08, 2023 |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION