



# INSTRUCTION TO SERVICE

ITS-60660		March 4, 2023
<b>SECTION:</b>	549-HVAC SYSTEM	
<b>WRITTEN BY:</b>	Mark Reitz	
<b>SUBJECT:</b>	Hose clamp replacement for Eberspaecher auxiliary heater fuel supply lines.	
<b>ISSUE:</b>	Coach auxiliary heater installations have been found with the incorrect size hose clamps on the fuel supply lines.	
<b>SUMMARY:</b>	Performing this procedure will ensure the proper fuel line clamps are being used.	


# ITS-60660

Ref. NHTSA Recall No.	Ref. Transport Canada Recall No.
Not Applicable	Not Applicable

**THIS ITS DOCUMENT SHOULD BE RETAINED AND REFERRED TO FOR FUTURE MAINTENANCE UNTIL THE PARTS AND/OR SERVICE MANUAL IS UPDATED TO REFLECT WORK DONE AS A RESULT OF THIS DOCUMENT. ENSURE THAT THIS DOCUMENT IS AVAILABLE FOR PARTS AND MAINTENANCE STAFF GOING FORWARD.**

## PROCEDURE:

1. Set park brake and chock wheels.
2. Turn the main battery disconnect switch to the "OFF" position.
3. Ensure the engine has cooled down to room temperature.
4. Locate the six (6) hose clamps attached to the auxiliary heater fuel supply hoses. Remove and discard existing clamps.
5. Install new hose clamp, PN 8410272, at all six (6) locations. Torque hose clamps to 12-14 IN-LBS.



6. Start coach and the auxiliary heater and check for leaks.



**LABOUR ESTIMATE**

	Operation	Number of Technician(s)	Hours	Labor Time T X HR
1	Replace hose clamps on aux heater fuel hoses.	1	1	1

**PARTS REQUIRED**

Item	Part Number	Description	Qty. per Coach	Units	Notes
1	8410272	Hose clamp	6	EA	

**SPECIAL TOOLS REQUIRED**

Item	Part Number	Description	Qty.	Units	Notes
1					