

SERVICE ACTION

Reference number:	SA-01-1735	Issued: 01 March, 2023
Subject:	Install the Correct Sill Plaques	
Model:	V12 Vantage Roadster	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Action

Aston Martin has found that some V12 Vantage Roadster vehicles have the incorrect sill plaques installed.

- Incorrect sill plaques show: "XXX of 254".
- Correct sill plaques show: "XXX of 249".

Do the workshop procedure that follows to install the correct sill plaques.

Workshop Procedure

1. Remove the right side front sill scuff-plate (refer to Workshop Manual Procedure 01.05.AJ).
2. Use an applicable tool to remove the incorrect sill plaque from the right-side front sill scuff-plate.
3. Use a suitable solvent to remove any remaining glue from the sill scuff-plate.
4. Install the correct sill plaque to the right-side front sill scuff-plate.
5. Install the right side front sill scuff-plate (refer to Workshop Manual Procedure 01.05.AJ).
6. Remove the left side front sill scuff-plate (refer to Workshop Manual Procedure 01.05.AK).
7. Use an applicable tool to remove the incorrect sill plaque from the left side front sill scuff-plate.
8. Use a suitable solvent to remove any remaining glue from the sill scuff-plate.
9. Install the correct sill plaque to the left side front sill scuff-plate.
10. Install the left side front sill scuff-plate (refer to Workshop Manual Procedure 01.05.AK).

Warranty Data

Procedure and Labour Time

Description	Labour Time
Install the Correct Sill Plaques	0.10

Part Data

The parts necessary for this repair will be issued to all affected Dealers on 01st March 2023.

To contact Aston Martin for further information about this document, please refer to the "Contact Us" page in Technical Hub.