



INFINITI

TECHNICAL SERVICE BULLETIN

Classification: EL21-023B	Reference: ITB21-030B	Date: March 14, 2023
------------------------------	--------------------------	-------------------------

COMBINATION METER MODULES OR ABS CONTROL UNITS CANNOT BE SWAPPED

This bulletin has been amended. See AMENDMENT HISTORY on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2022-2023 QX60 (L51)

SERVICE INFORMATION

Do not swap the combination meter module or ABS control unit between vehicles listed in **APPLIED VEHICLES**, for any reason.

Due to a new electrical architecture, the vehicle mileage is now stored in the combination meter module and the ABS control unit. This value cannot be updated manually.

When a mileage difference is detected between these two modules, the module with the lower value will be immediately overwritten, replacing it with the higher mileage. This cannot be undone.

If a new combination meter module or ABS control unit is installed, it will automatically be overwritten to the correct vehicle mileage.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 14, 2021	ITB21-030	Original bulletin published
January 3, 2022	ITB21-030A	SERVICE INFORMATION updated
March 14, 2023	ITB21-030B	APPLIED VEHICLES updated

