



## MAZDA DEALER EMAIL

---

Attention Service, Sales and Parts Department,

A Technical Service Bulletin (TSB 08-001/22 - AIR BAG WARNING LIGHT ON WITH DTC B1126:13 OR B1127:13) has been released to repair 2019-2022 Mazda3 with DTC B1126:13/B1127:13. Follow the TSB to repair the vehicle before replacing the airbag module.

MC is working on a separate TSB for 2020-2022 CX-30.

Please have your technician call Hotline on any cases concerning CX-30 with these DTCs.