# **Technical Service Bulletin**



**91 Parking aid not working due to environmental influences, DTC B10FCF0/B107BF0** 91 23 80 2069694/1 March 15, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, S3, RS 3, Q4 e-tron, Q4 Sportback e-tron	2022 - 2024	All	Not Applicable

### **Condition**

#### **Customer states:**

The warning message "Front/rear parking aid: Sensor view restricted because of environmental factors" appears in the instrument cluster.

#### Workshop findings:

• The message is reproducible.

#### And/Or

One of the following DTCs are stored in the parking aid control module, -J446- (address word DA0076):

- DTC B107BF0 (Rear parking aid sender, malfunction because of environment influences) with symptom code 1080304 or 13959168.
- DTC B10FCF0 (Front parking aid sender, malfunction because of environment influences) with symptom code
   1113328 or 13959169.

## **Technical Background**

The new generation of ultrasound parking aid sensors are able to detect problems due to external influence such as dirt, ice, and external ultrasound signals.

When the system detects such problems the system is made temporarily unavailable in order to prevent false warnings to the driver. When this occurs a message is displayed to the driver in the instrument cluster.

Below are examples based on the symptom code found with DTC B107BF0 or B10FCF0:

- **Symptom 1080304 or 1113328:** Temporary partial availability of the system due to environmental influences (e.g. external ultrasound noises)
- **Symptom 13959168 or 13959169:** Temporary partial availability of the system due to environmental influences (e.g. dirt/ice)

### **Production Solution**

Not Applicable

# Technical Service Bulletin



### **Service**

Perform the following checks on the respective ultrasound sensors (depending on DTC):

- Check for dirt, ice, foreign objects, stickers, and a properly fit license plate.
- Check for damage on the bumper, air intake grille, and underbody which indicates an impact during parking.
- Check for mechanical damage (stone chips and scratches).
- Check the fit of the sensors, bumpers, and trim in the surrounding areas.
- Check the measured values "Parking aid sender settling time in the parking aid control module, J446 (address word DA0076) for a cyclic/dynamic change of the respective measured values when approaching an obstacle.

**Scenario 1:** If the concern occurs sporadically: no further measures are necessary, as it is caused by environmental influences.

Note: In this case, replacement of the driver assistance systems -J446- (DA0076) without clear findings is not effective. Part replacement of the -J446- (DA0076) does not solve this issue. Claims for replaced parts will be subject to review.

**Scenario 2:** If the concern is reproduced or is static: One of the ultrasound sensors, mountings or circuits may be faulty. If this is the case, proceed with standard diagnosis.

**Note:** An indicator a malfunction may be present is a significantly increased frequency counter within the standard ambient conditions of the respective fault code.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

### **Additional Information**

All part and service references provided in this TSB (2069694) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.