



Tips and Tricks Revision 1

Date: March 10, 2023
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 1. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 1 New Additions		
#	Subject	Model Affected
1	Error C1134 – High DRL temperature (update)	Multistrada V4
2	Indications and precautions for lithium-ion batteries	DesertX
3	Possible clutch slipping	DesertX
4	Possible vibrations in left and right footpeg area	DesertX
5	Possible noise of Ohlins steering damper	All Models

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.