

SERVICE ACTION CAMPAIGN N766 & H427 BLANKING PLUG OIL LEAK

OWNER NOTIFIED SERVICE ACTION N766 H427 – BLANKING PLUG OIL LEAK

AFFECTED MODELS	21MY Range Rover Velar 21-22MY F-PACE
VOLUME AFFECTED	JAG US 2202 CAN 336 LR US 1675 CAN 588
REPAIR	On certain vehicles, the cylinder block vacuum pipe blanking plug may become detached, resulting in an engine oil leak and stress on crank case breather system. A replacement of the blanking plug is required.
REPAIR TIME	2.3 hrs + DIDO
CAMPAIGN LAUNCH	Jaguar - February 6th, 2023 Land Rover – February 22nd, 2023
Notes	Retailers should check the warranty portal to confirm affected VIN and following the service procedure, repair all affected unsold vehicles before sale and delivery. Customer vehicles should be repaired at the next service visit. All customers will be notified by mail and asked to contact their retailer for a service appointment.