

SERVICE ACTION CAMPAIGN N765 INCORRECT EMISSIONS LABEL INSTALLED

CUSTOMER SATISFACTION PROGRAM N765 – INCORRECT EMISSIONS LABEL INSTALLED	
AFFECTED MODELS	22MY and 23MY Range Rover 23MY Range Rover Sport
VOLUME AFFECTED	US 163
REPAIR	On certain Range Rover and Range Rover Sport vehicles, the Vehicle Emissions Control Information label wrongly states the code SCE. Retailers are to install the correct emissions labels on affected vehicles.
REPAIR TIME	0.3 hrs + DIDO
CAMPAIGN LAUNCH	February 21st, 2023
Notes	Retailers should check the warranty portal to confirm affected VIN and following the bulletin service procedure, inspect/repair all affected vehicles at the next service visit. Many affected vehicles have been repaired in ports, with 81 remaining that will need to be repaired by retailers.