

## Body/Chassis – Tailgate Anti-trap Sensor Replacements

### Issue:

- Tailgate anti-trap sensors are being replaced for power tailgates not power folding due to a false signal.

### Technical Description:

- Anti-trap sensors being returned for inspection/testing are not finding a fault with the sensors.

### Status:

- Poor connection between the anti-trap sensor and harness is suspected to be the potential cause.
- SSM75949 has been published aid in the diagnosis of an anti-trap sensor circuit issue and to request an EPQR be submitted with pictures of the sensor to harness connections.

18-22MY Range Rover (L405)

