

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Electrical

Topic: TCU not booting after sleep cycle information

Condition: N/A

Diagnostic Trouble Codes: N/A

Measure

If you have any of the following symptoms please raise a TR for further assistance.

TCU Not Booting Symptoms

- Cluster and centre screen time display 00:XX – XX incremented from time of last ADI wake
- System Communication Fault cluster message
- Yellow triangle – airbag fault
- No DoIP access to TCU. Can be seen on MDS2 as not reading control unit
- No 2 second SOS button LED illumination when transitioning into IGN5 (EU and ROW vehicles)

Parts Information

N/A

Attachments

N/A

KA Update Information

15/03/2023 - First Release

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.