

<b>Reference</b>	SSM75965
<b>Models</b>	Defender / L663 Discovery Sport / L550 New Range Rover / L460 New Range Rover Evoque / L551 New Range Rover Sport / L461 Range Rover / L405 Range Rover Sport / L494 Range Rover Velar / L560
<b>Title</b>	PHEV cooling circuit expansion tank level low or HV battery warning message displayed.
<b>Category</b>	Engine
<b>Last modified</b>	13-Mar-2023 00:00:00
<b>Symptom</b>	402000 Cooling System Concerns
<b>Content</b>	<p><u>Issue:</u> Jaguar Land Rover (JLR) are investigating customer reports of Plug-in Hybrid Electric Vehicles (PHEV)s exhibiting a low coolant fluid level within the HV cooling circuit expansion tank and/or a HV battery warning message displayed on the Instrument Panel Cluster.</p> <p><u>Cause:</u> Unknown at this time.</p> <p><u>Action:</u> Complete the following actions.</p> <ol style="list-style-type: none"> <li>1. Confirm the vehicle symptoms as reported.</li> <li>2. Before performing any diagnostics or a coolant level top up, raise a Technical Assistance (TA) and await further assistance. Attach the following item to the TA: <ul style="list-style-type: none"> <li>• SSM reference within the customer concern field and quoting PTS_130, which will be escalated directly to engineering.</li> </ul> </li> </ol> <p>Thank you in advance for your assistance with this matter.</p>

anBhdHRIcm7MjAyMy0wNC0wNVQxND0oMzo1NS42MTBaOzEzN4yMjYyNzluMTE3Ow==