

SSM 51502

2023 F-Super Duty - Navigation - Intermittent Audible Chime Heard While Driving

Some 2023 F-Super Duty vehicles equipped with navigation may exhibit an intermittent audible chime while driving with active trailer profile. This may be due to the trailer navigation informing the driver of forthcoming bridges. Visual indicators appear on the map when center display screen is on the navigation domain. No visual indicators appear while other screens are active. This may be due to the APIM software. Replacement or reprogramming of the APIM may not resolve this condition. Engineering is currently working on a solution and will be released via an over the air (OTA) software update expected in Q2 2023. It is recommended that customers should verify automatic updates are enabled and that the vehicle has been run long enough to receive updates via OTA. Continue to monitor OASIS.