# WNH9 Workshop campaign — Replacing front cover on steering wheel

## WNH9 Workshop campaign - Replacing front cover on steering wheel

ID Number WNH9

Models Panamera (971)
Model Years 2021 - 2022
VIN List Attached

Number of Affected VINs 99

Issue Description An incorrect variant of the cover on the front steering

wheel was installed on the affected vehicles due to an

error in the parts list.

For this reason, the cover on the front steering wheel on the affected vehicles must be replaced by a cover

in high-gloss carbon.

What Dealers Should do Please arrange for this measure to be carried out as

soon as possible on affected vehicles. As of the time of this posting (3/17/23), the repair is immediately

available.

Parts can be ordered via PPL as needed.

TI Number No. 127-22

Every vehicle is assigned exactly to one campaign scope.

To find out which scope is assigned to the relevant vehicle, see PCSS Vehicle Information.

Scope 1: Cover, black/black

Scope 2: Not valid

Scope 3: Cover, agate grey/black Scope 4: Cover, saddle tan/black

Scope 5: Cover, marsala red/black

Scope 6: Cover, black/truffle brown

Scope 7: Cover, cohiba brown/black

The part numbers of the parts required for the respective vehicle can be seen in the assigned scope.

### **Required parts**

Part number	Designation	Quantity/vehicle	Parts return*
V04015001HJ	Cover, black/black	1 unit	No
or			
V04015001HN	Cover, agate grey/black	1 unit	No
or			
V04015001HP	Cover, saddle tan/black	1 unit	No
or			
V04015001HM	Cover, marsala red/black	1 unit	No
or			
V04015001HK	Cover, black/truffle brown	1 unit	No
or			
V04015001HL	Cover, cohiba brown/ black	1 unit	No
and			
N 90799102	Countersunk screw with internal serration, M18 x 1.5 x 18	1 unit	No

<sup>\*</sup>The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the replacement parts process or be scrapped.

#### Warranty processing

Validity:

This workshop campaign will be carried out up to March 1st, 2028 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1 - 7:

Damage Code WNH9 66 000

Repair Code 2

Labor time 60 TU

Please note: Scope 2 is not valid, and invoicing is not possible under this scope.

#### **Customer mobility**

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle.

WNH9 Workshop campaign - Replacing front cover on steering wheel

Please invoice this additional service via WWS with the campaign scope.

#### **Attachments**

1. VIN\_List\_Report\_WNH9\_2023-03-17\_V2.xlsx