

Subject: Engineering Information - Power Tonneau Cover is Inoperable

This PI has been revised to end the need for gathering information from the field. Please discard PIE0736.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
GMC	HUMMER EV	2022	2023	—	—	—	—

If you encounter a vehicle with the above condition, refer to SI for diagnosis. GM Engineering is working on a solution. There will be a SUB Field Action to resolve these issues.

Version	2
Modified	Released February 10, 2023 Revised March 17, 2023 - Ended the need for gathering further information from the field.