



Service Bulletin

Bulletin No.: 23-NA-047

Date: March, 2023

INFORMATION

Subject: Dust, Snow or Water Around Fuel Filler Area

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2018	2024				
GMC	Terrain	2018	2024				
Holden	Equinox	2018	2020				

Involved Region or Country	United States, Canada, Mexico, Europe, Middle East, Israel, Palestine, Brazil (Mercosur), Chile (West), Ecuador (West), Paraguay (West), Peru (West), Cadillac Korea (South Korea), Thailand (ASEAN), Australia/New Zealand, Egypt, Other Africa
Additional Options (RPOs)	
Condition	Some customers may comment on an excess amount of dirt, snow or water that can build up around the fuel filler neck, and it may get into the fuel filler neck.
Cause	The cause of the condition may be when trucks are operated in a high amount of dirt, dust or snow which can migrate to the filler cap area.
Correction	Notify the customer that GM has made available a gas cap for drivers that operate in these environments. This will help to protect the fill area and the fuel system. This should NOT be charged to warranty. It is customer pay if they want to add the cap.



6295094

The cap pushes over the outside of the filler neck, and the tether is retained in the hole in the filler door arm, as shown in the photo.

Parts Information

Causal Part	Description	Part Number	Qty
X	CAP ASM - F/ TNK FIL	84689444	1

Version	1
Modified	Released March 20, 2023

