



# Preliminary Information

## PIC6496 MIL DTC P30EF

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2022 - 2023	All	All	2.0L (LSY)	All
Cadillac	CT5	2022 - 2023	All	All	2.0L (LSY)	All

Involved Region or Country	North America
Condition	Some Customers may see MIL illuminated and technicians may find DTC P30EF set in the ECM.
Cause	Hardware anomaly in cooling fan motor

### Correction:

Currently engineering is working on a fix and this PI will be updated with the solution.

### Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0542309	Engine Malfunction Indicator Lamp (MIL) Active - Customer Concern Not Duplicated (CCND)	0.3 *
*You may claim up to the allowable labor hours		

### Version History

Version	1
Modified	03/10/2023 - Created on.



GENERAL MOTORS