



## Preliminary Information

### PIP5905 Malfunction Indicator Lamp (MIL) illuminated in the Driver Information Center (DIC) With P0299 Stored.

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022	All	All	Equipped with 2.7L (L3B)	All
Chevrolet	Silverado 1500	2023	All	All	Equipped with 2.7L (L3B)	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022	All	All	Equipped with 2.7L (L3B)	All
GMC	Sierra 1500	2023	All	All	Equipped with 2.7L (L3B)	All

Involved Region or Country	North America
Condition	Some customers may comment on a Malfunction Indicator Lamp (MIL) illuminated in the Driver Information Center (DIC). Technicians may find DTC P0299 may be stored Current or in recent history.
Cause	P0299 Improved Diagnostic Sensitivity

#### Correction:

Some customers may comment on a Malfunction Indicator Lamp (MIL) illuminated in the Driver Information Center (DIC) with DTC P0299 may be stored Current or in recent history.

If no other engine performance, induction or turbocharger related codes are stored, an updated Engine Control Module calibration to correct this issue is scheduled for release.

Until the calibration is released, advise the customer that operating the vehicle in Tow Haul mode may temporarily reduce the recurrence of the DTC.

#### Version History

Version	1
Modified	03/14/2023 - Created on.



GENERAL MOTORS