



Bulletin No.: PIP5912  
Published date: 03/22/2023

# Preliminary Information

PIP5912 LZ0 setting DTCs P0402 P049C P054E P1089 P140C P149A P2203 P22A1 P23AF P242B P2459 P2463 and/or P261F

## Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2023	All	All	LZ0 (3.0L)	All
GMC	Sierra 1500	2023	All	All	LZ0 (3.0L)	All

Involved Region or Country:	North America
Condition:	Customer may complain of a MIL on the DIC.
Cause:	A technician may see P0402, P049C, P054E, P1089, P140C, P149A, P2203, P22A1, P23AF, P242B, P2459, P2463, and or P261F. set in the ECM.

## Correction:

Perform normal SI diagnostics.

If the concern cannot be duplicated and the cause cannot be determined, engineering is investigating the root cause and dealers are asked not to replace components in an attempt to repair.

## Version History

Version	1
Modified	03/22/2023 - Created on.

