

Subject <b>Clutch Pedal Creak/Squeak Noise</b>		Market <b>USA</b>
Service Category <b>Drivetrain</b>	Section <b>Clutch</b>	
Applicability <b>20-23 Tacoma</b>		

**APPLICABLE VEHICLES**

2020-2023	Tacoma
-----------	--------

**CONDITION**

Some 2020-2023 Manual Transmission Tacoma vehicles may exhibit an abnormal clutch pedal creak/squeak sound during operation.

Clutch pedal Creak/Squeak Example



**RECOMMENDATIONS**

This issue is being investigated. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

**Prior to contacting TAS, confirm/attach the following to the case:**

1. Video of the sound duplicating
2. No previous repairs/lubrication of related clutch pedal parts
3. No separation of any clutch pedal parts has occurred
4. Temperature and humidity conditions during duplication

**LINK REFERENCES**

This Tech Tip does not contain any link references