

**Volvo Car USA LLC****Technical Journal**

Technical Journal Title		Ref. No.	
Left front LED flickers after turning car off - Check outer position bulbs		TJ 36584.1.1	
Issuer (Dept.)		Issue Date	Status Date
Technical Service		3/20/23	3/24/23
Car Market	Partner	Function Group	
United States and Canada	3 US 7510 Volvo Car USA	3520	
Function Description		Page	
Lighting, front		Page 1 of 3	

Attachment

File Name	File Size
Headlight LED TJ 36584.png	0.0934 MB
LED parking.mp4	9.2087 MB
Position bulb location.png	0.1422 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If customer has a complaint of the left front LED within the headlight assembly flickering after the car is turned off (See [attached video](#) for reference), please see service below.

CSC Customer Symptom Codes

Code	Description
FN	Exterior light front (excl headlight)/Daytime running lights/position lights do not work

DTC Diagnostic Trouble Codes**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
1XX							2008-2016		-	0-0

SERVICE:

If the symptom is confirmed please check outer position bulbs in both front headlights for proper operation.

Replace both position bulbs if found faulty. (See attachment)

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3520.

To view TJ attachments continue to next page. This TJ has two attachments and one video file.

